



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210

PO Box 145801

Salt Lake City, Utah 84114-5801

801-538-5340

801-359-3940 (Fax)

801-538-7223 (TDD)

Partial:___ Complete: XXX Exploration:___

Inspection Date & Time: 6/21/2000 / 10:00a.m.-4:00p.m.

Date of Last Inspection: 5/11/2000

Mine Name: Star Point Mine County: Carbon Permit Number: ACT/007/006

Permittee and/or Operator's Name: Plateau Mining Corporation

Business Address: 847 Northwest Highway 191, Helper, Utah 84526

Type of Mining Activity: Underground XXX Surface___ Prep. Plant___ Other___

Company Official(s): Johnny Pappas

State Officials(s): Steve Demczak, Wayne Western Federal Official(s): None

Weather Conditions: Warm, 70's

Existing Acreage: Permitted- 9,060 Disturbed- 220 Regraded-___ Seeded-___ Bonded- 220

Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___

Status: Exploration/ Active/ Inactive/ XXX Temporary Cessation/___ Bond Forfeiture

Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June)_____ (date)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 6/21/2000

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The permittee will be revising a map to show permit and disturbed area boundaries.

2. SIGNS AND MARKERS

Identification signs are in place where public roads interface with the permit boundary. Also, other signs include topsoil and refuse pile signs. Stream buffer zone sign marks the encroachment approved areas adjacent to streams. The disturbed boundary is marked. The permittee has marked each fuel and fluid tank as to content.

4A. HYDROLOGIC BALANCE: DIVERSIONS

There are approximately sixteen miles of constructed diversions within the disturbed and interfacing undisturbed area. This includes water conveyance systems of over 80 ditches and 32 culverts and berms that control and direct runoff. The diversions are designed. There was no water flowing in the ditches during the inspection. Several ditches appeared to have been recently cleaned out.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

There are nine sediment ponds and three water impoundments. The sediment ponds provide sediment control for the majority of the disturbed areas. There are four BTCA's. The runoff from these areas is treated and controlled by alternative sediment control measures. The water impoundments are associated with the coal wash plant. No hazardous conditions were noticed.

None of the sediment ponds were discharging during the inspection. Ponds 1, 2, 4, 5, 8, and 9 contained runoff; the remaining ponds were dry. Pond inspections for the second quarter were on file at the mine site, including last year's annual inspection.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Silt fences provide the sediment control on the BTCA areas. The mine has installed redundant sediment control measures including straw bales, silt fences, sumps, and check dams to retain sediment near the source.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The mine water monitoring report for the first quarter was submitted.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

UPDES reports for the first quarter showed the permittee was in compliance with the permit.

The permit number is UT0023769 became effective January 1, 1997 and expires on December 31, 2001.

INSPECTION REPORT
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/006

DATE OF INSPECTION: 6/21/2000

(Comments are Numbered to Correspond with Topics Listed Above)

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The coal mine waste disposal area, as approved by the Division, covers an area of approximately 69 acres. The refuse pile approved design includes outcrops not to exceed 2:1, an MSHA berm, a sloping pile with positive drainage, diversions designed to meet the 6 hr 100 year storm event, and a commitment on restricting non-coal waste and the storage of combustible materials within the refuse pile.

The first and second quarter inspection report was prepared by the permittee and was P.E. Certified. A copy was submitted to the Division. No hazardous conditions were reported.

8. NONCOAL WASTE

Non-coal waste is being stored in several areas. At this time, not all of the equipment brought from the underground mine has been classified as usable or as noncoal waste.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

All roads, both ancillary and primary, are designed and discussed in the MRP.

18. SUPPORT FACILITIES -

The permittee has a contractor dismantling the belt lines and feeders at the site.

20. AIR QUALITY PERMIT -

The permit number of the Air Quality Permit is DAQE 886-96

21. BONDING AND INSURANCE -

The general liability insurance form was reviewed and complies with the requirements of the R645 Coal Rules.

The Reclamation Agreement has been updated including the permit area as the bonded area. The permittee plans to make a change having the disturbed area as the bonded area.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Johnny Pappas (Plateau)

Henry Austin (OSM)

Given to: Pam Grubaugh-Littig (DOGM)

Filed to: Price Field Office

Date: June 26, 2000

Inspector's Signature: _____

Stephen J. Demczak

#39